

DISCHARGER

ACTON WPCP + LAGOON

TYPE

OWRA

CONTAMINANT

Total coliform

FACILITY ACTION

equipment being replaced

Information complete as of April 26, 2000

MOE ACTION

Assessment complete - no further action required